**ROTAX.** SERVICE INFORMATION

# **UL-Engines (2-stroke) fuel consumption**

In case of complaints about "high fuel consumption" first of all has to be checked whether this is

- due to performance demand

or

- due to a technical failure.

# 1) How much fuel is allowed for an engine if it is in good condition?

This mainly depends on the power output of the engine (=output requirement). This power requirement depends mainly on the aerodynamic quality of the aircraft (wire-based ultralight or streamlined experimental) and of the flight habits (high-speed flight, cruising, sportive flight).

### 1.1) Example no. 1:

-- performance demand P = 28 kW/37,5 hp (e.g. take-off power) (1 kW = 1,341 hp, 1 hp = 0,746 kW)

--- specific consumption, e.g. BSFC = 450 g/kWh = 0,45 kg/kWh

— Fuel density  $\phi$  (Rho) = 0,73 kg/litre

This results in a consumption "B" of litres per hour:

B =  $\frac{P \cdot BSFC}{\phi}$  =  $\frac{28 \cdot 0.45}{0.73}$  = 17,2 litres/h

This "absolute" consumption refers to a continuous engine power supply of 28 kW (= 37,5 hp). This consumption will seem extremely high for an ultralight aircraft but is realistically possible.

In practice the consumption will be considerably less, as the engine is run at full throttle (= max. engine performance e.g. 28 kW) only for a few minutes, and after take-off flight, when cruising altitude is reached, one continues at cruising speed.

## BOMBARDIER - ROTAX GESELLSCHAFT M.B.H. MOTORENFABRIK

A-4623 GUNSKIRCHEN — AUSTRIA Telefon: (07246) 271-0\*, Telefax: 43-7246-370 Telex: 25546 brgk a, Telegr.: Bombrotax Gunskirchen RO

- 2 -

**1.2) Example no. 2** (basic data as in example no. 1):

- 6 minutes for take-off and climb (full throttle) .....= 1,7 litres

-54 minutes at cruising speed at e.g. 15 kW (= 20,1 hp)

 $B = \frac{15 . 0.45}{0.73} \cdot \frac{54}{60} \cdot \frac{54}{0.000} = \frac{8.3 \text{ litres}}{10.0 \text{ litres/hour}}$ 

If the pilot, however, remains at "full throttle", the consumption will remain at 17 litres/hour.

In competition where minimum consumption is the criterion, consumption values of 4 to 6 litres/hour have been achieved. These values, however, must not be taken as a rule for common use, as these values are achieved by top-pilots under particular conditions.

#### Please note the following:

- Usual (common) specific consumption:

fan-cooled 2-stroke-engines	480 to 530 g/kWh
liquid-cooled 2-stroke-engines	400 to 460 g/kWh

- --- see ROTAX power/torque/consumption curves for each engine type with an "estimated" propeller as indicative values
- --- The power requirement increases considerably with increasing speed. This is shown in the following example:

#### **1.3) Example no. 3:**

15 kW for 60 km/h, however, already 35 kW for 80 km/h with the same air-craft i.e. the performance increases with the  $3^{rd}$  power of the speed.

$$\frac{P_2}{P_1} = \left(\frac{V_2}{V_1}\right)^3 \qquad P_2 = P_1 \left(\frac{V_2}{V_1}\right)^3 = 15 \left(\frac{80}{60}\right)^3 = 35 \text{ kW}$$

and the consumption increases accordingly.

NOTE: Full throttle results in maximum power at "nominal r.p.m." but 3/4 or 1/ 2 of throttle position does not mean 3/4 or 1/2 power.

Depending on engine type,	3/4 throttle	means	95 % power
	1/2 throttle	means	80 % power
	1/4 throttle	means	50 % power
	1		

as approximate indicative values.



## 2) Possible mistakes causing high fuel consumption:

If a check as per para. 1) should result in considerably less consumption as measured in fact, the reasons may be the following:

- a) Intake- and exhaust-system does not correspond with original ROTAX configuration.
- b) air filter very dirty
- c) the propeller is not correctly matched to the engine
- d) carburettor float does not hold fuel level:
- carburettor float valve is too wide open because of dirt
- float level incorrectly adjusted
- extreme vibrations (engine mounts, unbalanced propeller, inadequately suspended intake silencer) keep the float valve open
- too high pressure in fuel system (max. 0,5 bar allowed, should be 0,3 bar).
- carburettor float valve defective
- bad carburettor vent (see Installation Instructions)
- e) Carburettor of a different engine type has been fitted or wrong jets have been installed.
- f) Incorrect carburettor jetting

### 3) Conclusion:

In any case a specialized technician has to find the reason for excessive fuel consumption. It is not allowed "just" to change carburettor jets.

The reflexions as per para. 1) are particularly important if a pilot has changed from a low performance craft to a more powerful aircraft.

MEMBER: FUELCONS 1987 07 22 Ve / Ws / Wa